

NASA

SECTION 40



Safety & Mission Assurance		Presenter	M. D. Ermingier
		Date	January 14, 2003
		Page	1

STS-107

Pre-Launch Mission Management Team Review



Safety & Mission Assurance		Presenter	M. D. Erminger
		Date	January 14, 2003
		Page	2

Approach and General Description

S&MA held reviews in preparation for the STS-107 Flight Readiness Review on 20 December 2002, 7 January and 10 January 2003 and is ready to proceed toward launch countdown.

PMNT Briefing Overview

- Significant Assessments – *discuss*
- Following the STS-107 FRR:
 - No open NSRS items applicable to STS-107 have been identified.
 - No new accepted risk hazards have been identified.
 - No new criticality 1 CLs have been identified.



Safety & Mission Assurance		Presenter	M. D. Erminger
		Date	January 14, 2003
		Page	3

Significant Assessments

ORBITER

- OV-103 BSTRA Crack



Safety & Mission Assurance	
Presenter	M. D. Erminger
Date	January 14, 2003
Page	4

STS-107 Concurrency Statement

S&MA has reviewed the status of preparation for this mission and has performed an independent assessment of the readiness of the Space Shuttle program for the conduct of this mission. We are in concurrence with proceeding with this mission.

Isl Yolanda Marshall
 SR&QA Director, JSC

Isl Shannon Bartell
 Director, KSC Safety, Health
 and Independent Assessment

Isl Amanda Goodson
 S&MA Director, MSFC

Isl Bill Higgins
 Chief, Shuttle S&MA, KSC

Isl Mark Erminger
 SS SR&QA Manager

Isl Mike Smiles
 S&MA Manager, SSC

Mission Management Team L-1 Day Review
January 15, 2003

Agenda

Introduction

Manager, Launch Integration

Mission Operations

Director, Mission Operations
APM, Flight Operations, SFOC

EVA

Manager, EVA Project

Flight Crew

Director, Flight Crew Operations

Space and Life Sciences

Director, Space and Life Sciences

Program Integration

Flight Manager
Manager, Space Shuttle Systems Integration
Manager, Space Shuttle Customer and Flight Integration
Manager, Space Shuttle KSC Integration
APM, Program Integration, SFOC

Payload Processing

Director of ISS/Payloads Processing

External Tank

Manager, External Tank Project

RSRM

Manager, Reusable Solid Rocket Motor Project

SRB

Manager, Solid Rocket Booster Project
APM, SRB Element, SFOC

SSME

Manager, Space Shuttle Main Engine Project

Vehicle Engineering

Manager, Space Shuttle Vehicle Engineering
APM, Orbiter Element, SFOC
APM, FCE/EVA, SFOC

Ferry Readiness

Ferry Operations Manager

Shuttle Processing

Director of Shuttle Processing, KSC
APM, Ground Operations, SFOC

Range

United States Air Force

DDMS

Commander, DOD, Manned Space Flight Support Office

Launch Weather

45th Weather Squadron

Landing Weather


National Weather Service

SS SR&QA

Manager, Space Shuttle Safety, Reliability & Quality Assurance

Readiness Poll

Manager, Launch Integration




**EVA
PROJECT
OFFICE**



Strontium Chromate in EMU Investigation Results

STS 107 L-1 Review

**G. Allen Flynt
EVA Project Office
Johnson Space Center
1/15/03**




EMU Systems Investigation



- **Background**

- During life extension evaluation of the I-145 Relief Valve on the fleet leader EMU (19 years of age) approximately 0.25 mg of Strontium Chromate (SrCrO_4) was identified
- Strontium Chromate is a carcinogen and poses a possible health risk if in the ventilation loop
- This valve is connected to the ventilation loop, however is not in the direct flow path to the crewmember.
- Strontium Chromate exists within the EMU System as a minor component (2%) of BR-127 Primer (MIL-P-23377)
- BR 127 primer is utilized on the water tank structure and aluminum horn, both of which are exposed to the ventilation loop. The primer is then over-coated with PD George for corrosion prevention.
- Over time water can leach SrCrO_4 out of exposed BR 127




**EVA
PROJECT
OFFICE**

EMU Systems Investigation



- **Findings associated with BR 127 use in the Water Tank**
 - Neoprene water bladders installed on EMUs prior to 1990 allowed water to leach into the water tank structure. Corrosion of the water tank and flaking of coatings was not uncommon
 - A flow path between the water tank and I-145 exists and would explain for the contamination exhibited on the EMU fleet leader (PLSS 1008)
 - Post 1990 installation of Flourel bladders eliminated water access to the water tank structure
 - All EMU water tanks are inspected every 2 years to ensure no exposure of BR 127
 - The migration of contamination into the ventilation loop is not considered possible
 - The I-145 Relief Valve is no longer functional during EVA operations and is not a functional part of the ventilation loop




**EVA
PROJECT
OFFICE**

EMU Systems Investigation



- **Findings associated with BR 127 use in the Aluminum Horn**
 - The Aluminum Horn is not considered to be a contamination source
 - This item is inspected every 2 years
 - No failure history associated with loss of coatings and exposure of BR 127
- **EMU Systems Conclusion**
 - Introduction of SrCrO₄ into the EMU ventilation loop during EVA is considered improbable



Toxicology Investigation of SrCrO₄



- **Toxicology Findings**
 - Strontium Chromate is a carcinogen and long term exposure above the industry standards is considered to increase the risk of cancer
 - Current industry standards for acceptable long term daily exposure to SrCrO₄ range from 0.002 mg/m³ to 0.2 mg/m³
 - JSC Toxicology has determined that in the improbable event that the 0.25 mg of SrCrO₄ found in the EMU fleet leader were released into the ventilation loop for the duration of a single EVA the crewmember would be exposed to the equivalent of 1 hour to 12 days of the daily limit for repeated long term career exposure

- **Toxicology Conclusion**
 - JSC toxicology has determined this type of exposure to be a minimal risk to crew health and does not represent an appreciable increase in risk in performing EVA operations

VEHICLE ENGINEERING



STS-107 L-1 DAY REVIEW

	Presenter:
	Organization/Date: Orbiter 01/15/03

ORBITER	To Be Presented
GFE	No Constraints
SOFTWARE	No Constraints
FCE	No Constraints
FLIGHT READINESS STATEMENT	To Be Presented
BACKUP	

107jp2cor.ppt 01/15/03 7:15am



VE-2



**STS-107
L-1 DAY REVIEW**

January 15, 2003

ORBITER



AGENDA	Presenter:
	Doug White
Organization/Date:	Orbiter 01/15/03

Waivers and Exceptions

No Constraints

Special Topics

To Be Presented

- FRR CoFR Exception Resolution – BSTRA Ball Cracks



VE-4



STS-107 L-1 DAY REVIEW

	<p>Presenter:</p> <p>Organization/Date: Orbiter 01/15/03</p>
--	--

SPECIAL TOPICS

107j2exr.ppt 01/15/03 7:15am



VE-5



STS-107 L-1 DAY REVIEW

**SPECIAL TOPICS FOR THE
STS-107 L-1 DAY REVIEW**

Presenter:
Doug White

Organization/Date:
Orbiter 01/15/03

Topic

- BSTRA Ball Cracks

Presenter

David Rigby

107j02cor.ppt 01/15/03 7:15am



VE-6



**BSTRA Ball -
Assessment of Crack Offset/Step**

Jan 14, 2003

M. Dunham



Background

- **Traction test was run on 2.24" severely cracked ball (HB#2a) with 0.450mil "step" with no increase in friction compared to uncracked ball**
 - Within the original criteria of 0.500mil
- **Subsequently, a 1.75" severely cracked ball was identified as having 0.970mil step**
 - Ball cannot be tested as it was destructively sectioned
- **BSTRA ball and insert (aka cup) are both treated with a baked-on coating of Vitrolube for lubrication**
 - Each side has 0.5 to 0.9mil of Vitrolube
- **Ball and insert have closely matched diameters with gap almost completely filled with Vitrolube**
 - Edge of cup has a minimum of 10mil radius
- **BSTRA team looked at range of expected step values**
 - Increasing criteria from .5mil to 2mil considered sufficient to cover maximum step

1/15/2003


2

Ball/Insert Dimensioning Provides Very Tight Fit

System	Line Type	Ball Diameter	Insert Diameter	Max Gap w/o Vitrolube	Min Gap w/o Vitrolube	Max Gap w/ Vitrolube	Min Gap w/ Vitrolube
LOX	I	2.2400	2.2435	0.0037	0.0032	0.0017	-0.0004
		2.2398	2.2432				
LH2	II, III, IV	1.7500	1.7535	0.0037	0.0032	0.0017	-0.0004
		1.7498	1.7532				
LH2	I, II, III, IV	1.2500	1.2535	0.0037	0.0032	0.0017	-0.0004
		1.2498	1.2532				

Note

Vitrolube thickness equal to 0.005" to 0.009"



1/15/2003

Kinematics of BSTRA Joint

- **Rotation of joint can be achieved by sliding on either cup side**
 - Slip will occur normally on side with lower friction
 - Increasing friction on one surface only will not interfere with function
- **Angulation of joint occurs only along “longitude” lines**
 - Torsional motion is restrained by bellows
 - Cracks (with steps) that are aligned with longitude will provide minimal erosion or friction
- **Crack step must be oriented UNDER the cup to affect friction**
- **Or, step must bear against edge of cup**
 - Minimum edge radius should prevent step in open “equator” from hanging up cup




Crack Considerations

- **Maximum offset or step height is expected away from crack tips – not a constant height**
 - Between tips, especially near initiation point, is where crack is deepest, widest
 - Tips have continuity of material just beyond tip to minimize step
- **Test crack steps are considered reasonable upper bound**
 - Severe, deep cracking performed outside of cups
 - ◆ Cups produce smaller, shallower cracks and provide constraint against excessive step height
- **Compressive forces normally found between tight fit cup and ball will be concentrated on higher side of step at a discontinuity**
 - Elastic deformation will tend to close the crack and move toward smooth surface



“Step” Vitrolube Interaction

- Original criteria was simple (and conservative) as it allowed reduction of Vitrolube to achieve leveling of step without exposing bare ball to Vitrolube on the cup side (creating friction)
- Two ways available to close step
 - Force between cup and ball elastically deform ball
 - Same forces can grind some of vitrolube on high side of step



1/15/2003

6

Material Considerations

● FOD Liberation

- Reason we are seeing fines at the crack face may be due to this offset.
- Mechanism for FOD generation does not change

● Material properties of Vitrolube

- Glass material applied at high temperature
 - ♦ Cracks with the ball
 - May grind off in very small pieces (no flaking), does not flow like plastic
 - Traction test of 0.45 mil step produced burnishing of Vitrolube only
- ## ● GALLING / WEAR: IF, surfaces wear through Vitrolube... Stooddy #2 is designed for high wear and galling resistance.
- Ball with 970 micro-inch offset was tested through 50 cycles at nominal load (without Vitrolube)... with cracks located randomly under cups. Inspection of the cups/ball did not show galling/chafing.

Allowable Step Criteria Increased to 2 Mil

- **Elastic deformation of ball surface will provide for more than 1 mil of step**
- **Erosion of Vitrolube on both ball and cup is required prior to contact between Inconel cup and Stooddy ball**
 - **Min of 1 mil (0.5 each side) to max of 1.8 mil (0.9 each)**
 - ◆ **Friction during erosion expected to be small**
 - **Stooddy material selected to prevent galling**
- **Criteria of 2 mils selected as reasonable**
 - **Covers upper bound data of 0.97 mil from testing**
 - **Reasonable, conservative estimate in absence of hard test data**



STS-107 L-1 DAY REVIEW

	<p>Presenter:</p> <p>Organization/Date: Orbiter 01/15/03</p>
--	--

FLIGHT READINESS STATEMENT

107102ccaf.ppt 01/15/03 7:15am



VE-7





SSVEO Is Ready to Fly STS-107

ORBITER FLIGHT SOFTWARE FLIGHT CREW EQUIPMENT	Program Manager Shuttle Engineering Office	D. B. Stamp , TMR Software
ORBITER/FLIGHT	Program Director , SRMS Management Office	P. A. Petete , TMR Orbiter and Flight Crew Equipment
B. I. Bejtnik , Program NASA Systems The Boeing Company	J. Wilder , Associate Program United States	N/A
T. F. Peterson , Associate Program Flight Software Element United States	N/A	Research, Program Manager , SVS NEPTEC
J. F. Buchli , FCE/EVA Associate Program Manager United Space Alliance	Ralph R. Roe , Manager Space Shuttle Vehicle Engineering	D. L. McCormick , Ferry Flight Manager